

**Cutting Tips • Two Piece Liquid Air Fuel Gas, MAPP® & Propylene**



**Series 1 MTHM**

High speed machine cutting thru 10"/252mm.

Size	Part No.
00	0333-0339
0	0333-0340
1	0333-0341
2	0333-0342



**Series 1 GPP**

General purpose hand and machine cutting torches.

Size	Part No.
00	0333-0261
0	0333-0262
0	0387-0154CS
1	0333-0263
1	0387-0155CS
2	0333-0264
2	0387-0156CS
3	0333-0265
4	0333-0266
5	0333-0267
6	0333-0268

**Series 3 GPP**

General purpose hand and machine cutting torches.

Size	Part No.
0	0333-0390
0	0387-0164CS



**Series 1 MTHP**

High speed machine cutting thru 10"/252mm.

Size	Part No.
00	0333-0352
0	0333-0353
1	0333-0354
2	0333-0355
3	0333-0356
4	0333-0357



**Series 1 HPP**

Heavy preheat for scrap, bevel & other heavy preheat requirements.

Size	Part No.
4	0333-0286



**Series BTMP**

High performance bevel cutting for use with MAPP & propylene gases.

Size	Part No.
4	0333-0209
5	0333-0210
6	0333-0211

**Cutting Tips, One Piece • Propane & Natural Gas**



**Series 1 1-200**

General purpose hand and machine cutting.

Size	Part No.
1	0330-0144
2	0330-0145



**Series 1 1-200L**

General purpose extra length tips.

Size	Part No.
4	0330-0537



**Series 1 1-207**

Using for "blowing" rivets. Popular with various railroad

Size	Part No.
4	0330-0166



**Series 1 1-218**

Deseaming, gouging, weld preparation, removing defective welds, and washing rivets.

Size	Part No.
4	0330-0178
6	0330-0179



**Series 1 1-234**

Cutting close to bulkheads, rivet cutting, etc.

Size	Part No.
2	0330-0341




**Series 1 MCN**

For applications requiring extra heavy preheat and wide kerf.

Size	Part No.
6	0330-0543

Example: Demolition, ripping & RR car repair. 3/8"/9.75mm hose required minimum 80 PSIG oxygen and 15 PSIG fuel at torch.



**Series 1 HDNL**

For extra heavy duty cutting torches, emergency billet cutting, caster cut-off, steel mill scap cutting, foundry

Size	Part No.
8	0330-0554
10	0330-0547
12	0330-0548